

General Environmental Incident Summary

Incident: 3599 **Date/Time Notice:** 1/5/2015 1610 **DEM Incident No:**
Responsible Party: Plains Marketing
Date Incident: 1/5/2015 **Time Incident:** 0100 **Duration:** 1 minutes
County: Mountrail **Twp:** 153 **Rng:** 91 **Sec:** 23 **Qtr:**
Lat: 48.06544 **Long:** -102.34860 **Method:** Navigation quality GPS
Location Description: 4498 Hwy 8 Newtown, ND 58763

Submitted By: Daniel Holli **Affiliation:**
Address: P.O. Box 708
City: Belfield **State:** ND **Zip:** 58622

Received By:

Contact Person: Daniel Holli
P.O. Box 708
Belfield, ND 58622

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Cam-Loc connector leak

Description of Released Contaminant: Crude oil

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Camlock ears came loose allowing oil mist out of a hose connection while unloading an oil truck at the station.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Mist on surface of snow

Action Taken or Planned:

Oil mist was removed off the snow and solidified with soil for disposal.

Wastes Disposal Location: Sawyer landfill

Agencies Involved:

Updates

Date: 1/5/2015 ***Status:*** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted areas not associated with E & P. Followup is necessary.

Date: 4/13/2015 ***Status:*** Reviewed - No Action Required

Author: Martin, Russell

Updated Volume:

Notes:

Further review of incident report. A small volume spilled at an unloading station for Robinson Lake Gas Plant, where it is unlikely to impact surrounding waters. No followup is necessary.